

Installations- und Gerätetester

TESTBOY TV 455

Installation tester DIN VDE 0100-600

As its small brother, the TV 445, the Testboy TV 455 is suitable for testing in accordance with DIN VDE 0100-600. However, it has additional integrated test lead calibration. Due to the USB interface, the measurement results can be easily evaluated using the PC software supplied. Furthermore, it enables testing AC/DC sensitive RCDs TYPE B.

How you benefit:

| Check in accordance with DIN VDE 0100-600, ÖVE E8001, NIN/NIV | USB interface and PC software | Testing AC/DC sensitive RCDs (TYPE B) | Integrated test lead calibration | Log in accordance with ZVEH (option)

Specifications

Display 128 × 64 pixels with backlighting and integrated Good/Bad indication Scope of Delivery Incl. universal test cable 3 × 1.5 m, test cable for shockproof sockets, test probes, crocodile clips, mains adapter and batteries, carry strap, quick guide, CD with PC software, factory calibration certificate and carrying case Power Supply 6 × NiMH battery or battery AA Test voltage 50 V, 100 V, 250 V, 500 V, 1000 V Voltage measurement 0–550 V Earth resistance measurement 0–9999 Ohm Insulation resistance 0.15 MOhm to 1 GOhm Contact voltage RCD-Uc 0–100 V Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Housing Robust plastic with integrated magnetic clamp	Technical Data	TESTBOY TV 455
shockproof sockets, test probes, crocodile clips, mains adapter and batteries, carry strap, quick guide, CD with PC software, factory calibration certificate and carrying case Power Supply 6 × NiMH battery or battery AA Test voltage 50 V, 100 V, 250 V, 500 V, 1000 V Voltage measurement 0–550 V Earth resistance measurement 0–9999 Ohm Insulation resistance 0.15 MOhm to 1 GOhm Contact voltage RCD-Uc 0–100 V Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Display	
Test voltage 50 V, 100 V, 250 V, 500 V, 1000 V Voltage measurement 0–550 V Earth resistance measurement 0–9999 Ohm Insulation resistance 0.15 MOhm to 1 GOhm Contact voltage RCD-Uc 0–100 V Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Scope of Delivery	shockproof sockets, test probes, crocodile clips, mains adapter and batteries, carry strap, quick guide, CD with PC software, factory calibration
Voltage measurement 0–550 V Earth resistance measurement 0–9999 Ohm Insulation resistance 0.15 MOhm to 1 GOhm Contact voltage RCD-Uc 0–100 V Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory Interface USB	Power Supply	6 x NiMH battery or battery AA
Earth resistance measurement Insulation resistance O-9999 Ohm Contact voltage RCD-Uc O-100 V Release Time O - 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature O-40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory Interface USB	Test voltage	50 V, 100 V, 250 V, 500 V, 1000 V
Insulation resistance 0.15 MOhm to 1 GOhm Contact voltage RCD-Uc 0–100 V Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Voltage measurement	0–550 V
Contact voltage RCD-Uc Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Earth resistance measurement	0-9999 Ohm
Release Time 0 – 2500 ms Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Insulation resistance	0.15 MOhm to 1 GOhm
Trip-out current 10 mA, 30 mA, 100 mA, 500 mA, 1000 mA Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values USB	Contact voltage RCD-Uc	0–100 V
Operating temperature 0–40 °C Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Release Time	0 – 2500 ms
Overvoltage protection CAT III 600 V, CAT IV 300 V Measurement value memory 1900 measurement values Interface USB	Trip-out current	10 mA, 30 mA, 100 mA, 500 mA, 1000 mA
Measurement value memory 1900 measurement values Interface USB	Operating temperature	0-40 °C
Interface USB	Overvoltage protection	CAT III 600 V, CAT IV 300 V
	Measurement value memory	1900 measurement values
Housing Robust plastic with integrated magnetic clamp	Interface	USB
	Housing	Robust plastic with integrated magnetic clamp





